

Detail available on website

HUB-Ku-DVB-S Equipment's (1 Rack) by Hughes		
S.No.	Name of equipment	Model & Make
1	Modulator	Radyne DM240
2	Timing Generator	Hughes
3	Servers	HP ProLiant DL360(DNCC, SATGW, Vision,Database,IPGW,SDL), CP Server-Motorola CPX-1200
4	Beacon tracking receiver AUPC	ENERTECH
5	Multiplexer	Scopus Codico RTM-3300
6	Encoder	Scopus Codico E-1000
7	Antenna	3.8 Mtr _
8	RFT(BUC+SSPA)	16W Agilis

Note:

1. Interactive network of Hub & 516 SIT (Satellite Interactive Terminals) is not functional and programmes are being telecast only on 3289 ROTs (Receive Only Terminals).
2. Presently some of the parts of Hub are malfunctioning.
3. Interested service provider may like to visit in this office (9:00 Am to 5:00 Pm) any working day to physically inspect the hub to check the faulty equipment's at his own cost and submit the appropriate solution within 15 days of EOI.
4. For any query may kindly contact Sh.Amritpal Singh 09855522216.

Amritpal Singh